



# Product Change Notice

PCN Number: 17-0414-01  
Issue Date: 11-APRIL-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**  
OEM-VRC7016X-L  
OEM-VRC7016X-H

**CHANGE CATEGORY:**

- |  |                                    |   |
|--|------------------------------------|---|
| <input type="checkbox"/> Material                            | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                              | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Bill of Materials |                                    |   |

**DESCRIPTION OF CHANGE:**

Bill of material updated to add 100uF cap at position C39 to improve voltage stability of the DDR power supply. The board has been updated from Mfg Part No. 410-20026-3E to 410-20026-3F as reflected on label affixed to the board and in the EEPROM.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** Effective Immediately

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) with any questions regarding this change.

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.