



Product Change Notice

PCN Number: 13-0313-02A
Issue Date: 05-06-2013

Exar Corporation

www.exar.com | Support: customersupport@exar.com

PRODUCTS AFFECTED:

SP3080EEN-L/TR, SP3080EEN-L, SP3081EEN-L/TR, SP3081EEN-L, SP3082EEN-L/TR, SP3082EEN-L, SP3083EEN-L/TR, SP3083EEN-L, SP3084EEN-L/TR, SP3084EEN-L, SP3085EEN-L/TR, SP3085EEN-L, SP3086EEN-L/TR, SP3086EEN-L, SP3087EEN-L/TR, SP3087EEN-L, SP3088EEN-L/TR, SP3088EEN-L

CHANGE CATEGORY:

- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> Material | <input checked="" type="checkbox"/> Process | <input type="checkbox"/> Package |
| <input type="checkbox"/> Design | <input checked="" type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input type="checkbox"/> Other (specify) | | |

DESCRIPTION OF CHANGE:

Qualified TSMC as an alternate foundry supplier.
Qualified Cu wire bonding assembly process at Carsem, Ipoh, Malaysia and ASE, Chung-Li, Taiwan.

IMPACT OF CHANGE:

Expect no change to form, fit or function of the part as a result of this die technology upgrade and specification improvement.

TARGET IMPLEMENTATION DATE: 1-MAY-2013

Please contact customer support (customersupport@exar.com) for sample date availability or qualification data

PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.