



# Product Change Notice

PCN Number: 14-1251-01  
Issue Date: 29-JANUARY-2015

**Exar Corporation**

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SP3224ECY-L/TR	SP3224EEY-L/TR	SP3225ECY-L/TR	SP3225EEY-L/TR
SP3224ECY-L	SP3224EEY-L	SP3225ECY-L	SP3225EEY-L

**CHANGE CATEGORY:**

- |  |                                    |   |
|--|------------------------------------|---|
| <input checked="" type="checkbox"/> Material                       | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                                    | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Assembly Site |                                    |   |

**DESCRIPTION OF CHANGE:**

Qualification of an alternate assembly site, Carsem Ipoh, for the 20L TSSOP using copper or gold wire bonding.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 29-APRIL-2015

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.