



# Product Change Notice

PCN Number: 13-0834-03A  
Issue Date: 05-NOVEMBER-2015

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:** See Page 2 for the list of products affected.

**CHANGE CATEGORY:**

- |                                                                    |                                    |                                           |
|--------------------------------------------------------------------|------------------------------------|-------------------------------------------|
| <input type="checkbox"/> Material                                  | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                                    | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Assembly Site |                                    |                                           |

**DESCRIPTION OF CHANGE:**

Qualification of ASE Malaysia for assembly of 28, 44, 68L PLCC packaged products.

**Additional information:** All Exar devices packaged in 44L and 28L PLCC were qualified as Moisture Sensitivity Level (MSL) 1. Therefore product assembled at ASE with shipping label MSL 1 are correct. Products are no longer required to be baked and dry packed in Moisture Barrier Bags per MSL 1 requirements when labeled as such. Qualification performed for the release of PCN 13-0834-03 support the upgrade to MSL 1.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 02-JULY-2014

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.



# Product Change Notice

PCN Number: 13-0834-03A  
Issue Date: 05-NOVEMBER-2015

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: customersupport@exar.com

**PRODUCTS  
AFFECTED:**

ST16C1450CJ28-F	ST16C1450CJ28TR-F	ST16C1450IJ28-F	ST16C1450IJ28TR-F	ST16C1550CJ28-F
ST16C1550CJ28TR-F	ST16C1550IJ28-F	ST16C1550IJ28TR-F	ST16C1551CJ28-F	ST16C1551CJ28TR-F
ST16C1551IJ28-F	ST16C1551IJ28TR-F	ST16C2450CJ44-F	ST16C2450CJ44TR-F	ST16C2450IJ44-F
ST16C2450IJ44TR-F	ST16C2550CJ44-F	ST16C2550CJ44TR-F	ST16C2550IJ44-F	ST16C2550IJ44TR-F
ST16C2552CJ44-F	ST16C2552CJ44TR-F	ST16C2552IJ44-F	ST16C2552IJ44TR-F	ST16C450CJ44-F
ST16C450CJ44TR-F	ST16C450IJ44-F	ST16C450IJ44TR-F	ST16C452CJ68-F	ST16C452CJ68PS-F
ST16C452CJ68TR-F	ST16C452IJ68-F	ST16C452IJ68PS-F	ST16C452IJ68TR-F	ST16C454CJ68-F
ST16C454CJ68TR-F	ST16C454IJ68-F	ST16C454IJ68TR-F	ST16C550CJ44-F	ST16C550CJ44TR-F
ST16C550IJ44-F	ST16C550IJ44TR-F	ST16C552ACJ68-F	ST16C552ACJ68TR-F	ST16C552AIJ68-F
ST16C552AIJ68TR-F	ST16C552CJ68-F	ST16C552CJ68TR-F	ST16C552IJ68-F	ST16C552IJ68TR-F
ST16C554DCJ68-F	ST16C554DCJ68TR-F	ST16C554DIJ68-F	ST16C554DIJ68TR-F	ST16C650ACJ44-F
ST16C650ACJ44TR-F	ST16C650AIJ44-F	ST16C650AIJ44TR-F	ST16C654CJ68-F	ST16C654CJ68TR-F
ST16C654IJ68-F	ST16C654IJ68TR-F	ST68C554CJ68-F	ST68C554IJ68-F	ST78C34CJ44-F
ST78C34CJ44TR-F	ST78C36ACJ44-F	ST78C36ACJ44TR-F	ST78C36CJ44-F	ST78C36CJ44TR-F
XR16C2550IJ-F	XR16C2550IJTR-F	XR16C2850CJ-F	XR16C2850CJTR-F	XR16C2850IJ-F
XR16C2850IJTR-F	XR16C2852CJ-F	XR16C2852CJTR-F	XR16C2852IJ-F	XR16C2852IJTR-F
XR16C850CJ-F	XR16C850CJTR-F	XR16C850IJ-F	XR16C850IJTR-F	XR16C854CJ-F
XR16C854CJTR-F	XR16C854IJ-F	XR16C854IJTR-F	XR16L2550IJ-F	XR16L2550IJTR-F
XR16L2552IJ-F	XR16L2552IJTR-F	XR16L2750CJ-F	XR16L2750CJTR-F	XR16L2750IJ-F
XR16L2750IJTR-F	XR16L2752CJ-F	XR16L2752CJTR-F	XR16L2752IJ-F	XR16L2752IJTR-F
XR16M2752IJ44-F	XR16M2752IJ44TR-F	XR16M554IJ68-F	XR16M554IJ68TR-F	XR16M564IJ68-F
XR16M564IJ68TR-F	XR16M654IJ68-F	XR16M654IJ68TR-F	XR16V2552IJ-F	XR16V2552IJTR-F
XR16V2652IJ-F	XR16V2652IJTR-F	XR16V2752IJ-F	XR16V2752IJTR-F	XR16V554IJ-F
XR16V554IJTR-F	XR16V564IJ-F	XR16V564IJTR-F	XR16V654IJ-F	XR16V654IJTR-F
XR68C192CJ-F	XR68C192CJTR-F	XR68C192IJ-F	XR68C192IJTR-F	XR68C681CJ-F
XR68C681CJTR-F	XR68C681J-F	XR68C681JTR-F	XR68C92CJ-F	XR68C92CJTR-F
XR68C92IJ-F	XR68C92IJTR-F	XR82C684CJ/44-F	XR82C684CJ-F	XR82C684CJTR/44-F
XR82C684CJTR-F	XR82C684J/44-F	XR82C684J-F	XR82C684JTR/44-F	XR82C684JTR-F
XR88C192CJ-F	XR88C192CJTR-F	XR88C192IJ-F	XR88C192IJTR-F	XR88C681CJ-F
XR88C681CJTR-F	XR88C681J-F	XR88C681JTR-F	XR88C92CJ-F	XR88C92CJTR-F

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.



# Product Change Notice

PCN Number: 13-0834-03A  
Issue Date: 05-NOVEMBER-2015

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

	XR88C92IJ-F	XR88C92IJTR-F			
--	-------------	---------------	--	--	--

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.